

EXTERIOR MATERIALS



NORTH WEST - MAIN ENTRY PERSPECTIVE

BODY
FIBER CEMENT LAP SIDING

1



ACCENT SHINGLE
FIBER CEMENT LAP SIDING

2



MAIN TRIM
FIBER CEMENT TRIM

3



BODY
VINYL LAP SIDING
ON EAST ELEVATION

1




ACCENT SHINGLE
VINYL LAP SIDING
ON EAST ELEVATION

2



ACCENT TRIM
FIBER CEMENT TRIM

4



EXTERIOR MATERIALS



NORTH WEST - MAIN ENTRY PERSPECTIVE

UNDERSIDE CANOPY
ALUMINUM CLADDING

1




LINKING PANEL
FLAT PANEL

2




MAIN ENTRY
METAL PANEL

3



MAIN ENTRY
STOREFRONT

4



MAIN ENTRY
STONE

5



EXTERIOR MATERIALS



SOUTH - COURTYARD PERSPECTIVE




EAST PERSPECTIVE

ROOF
ASPHALT SHINGLE



1

RAILING
CAP
PICKET STYLE



2



WINDOW
SINGLE HUNG



3

